

Medidas Simples T		Sección en mm. h	Sección en mm. b	Sección en mm. e
	KG/M			
25	1,42	25	25	3,5
30	1,84	30	30	4,0
35	2,42	35	35	4,5
40	3,08	40	40	5,0
45	4,16	45	45	5,5
50	4,62	50	50	6,0
60	6,48	60	60	7,0
70	8,65	70	70	8,0
80	11,13	80	80	9,0
90	13,83	90	90	10,0
100	17,06	100	100	11,0

Medidas Ues		Sección en mm. h	Sección en mm. b	Sección en mm. e	Sección en mm. e1
	KG/M				
40 x 20	3,03	40	20	4,0	5,0
50 x 35	4,10	50	25	4,5	6,0
60 x 30	5,39	60	30	5,0	6,0

Medidas Angulares		Sección en mm. b	Sección en mm. e
	KG/M		
20x3	0,92	20	3
25x3	1,16	25	3
30x3	1,62	30	3
35x4	2,17	35	4
40x4	2,52	40	4
40x6	3,66	40	6
45x5	3,52	45	5
50x5	3,92	50	5
50x7	5,36	50	7
55x6	5,23	55	6
60x6	5,64	60	6
60x8	7,37	60	8
65x7	7,21	65	7
70x7	7,68	70	7
70x9	9,69	70	9
75x8	9,31	75	8
80x8	10,02	80	8
80x10	12,38	80	10
90x9	12,56	90	9
100x10	15,60	100	10
100x12	18,51	100	12
110x8	14,04	110	8
120x11	20,70	120	11
120x12	22,46	120	12
150x14	32,86	150	14
150x15	35,15	150	15
150x18	41,70	150	18
180x18	50,54	180	18
200x20	62,30	200	20