


SIMPLES T Y FORMAS EN U



Medidas Simples T	KG/M	Sección en mm. h	Sección en mm. b	Sección en mm. e
25	1,42	25	25	3,5
30	1,84	30	30	4,0
35	2,42	35	35	4,5
40	3,08	40	40	5,0
45	4,16	45	45	5,5
50	4,62	50	50	6,0
60	6,48	60	60	7,0
70	8,65	70	70	8,0
80	11,13	80	80	9,0
90	13,83	90	90	10,0
100	17,06	100	100	11,0

Medidas Ues	KG/M	Sección en mm. h	Sección en mm. b	Sección en mm. e	Sección en mm. e1
40 x 20	3,03	40	20	4,0	5,0
50 x 35	4,10	50	25	4,5	6,0
60 x 30	5,39	60	30	5,0	6,0

Ferro Vallès
Ferros i Acers del Vallès, S.L.

Pol. Ind. Can Burguès
Ctra. C-155 de Sabadell a Granollers, Km. 6,3, Nave 12
08184 PALAU-SOLITÀ I PLEGAMANS
Tel. 93 864 08 21 - Fax 93 863 98 99
E-mail: ferrovalles@ferrovalles.es